

RECEIVING INSPECTION REPORT
HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA, CALIF.

No. 11083

RECEIVED FROM

Plant #9

DATE REC'D. 1-3-57

P.O. NO.

VENDOR PACKING SLIP NO.

CONTRACT
CODE NO.DRAWING
NUMBERDWG. DASH OR
STANDARD PART NO.DWG.
REV.LOT
NO.CLASS
NUMBEROPER
NUMBERBUY OUT
CODE NO.O ACCT. OR
W.O. NO.

R S.O. NO.

CHARGE TO
QUANTITY
RECEIVED

DRAWING NO. AND DESCRIPTION

QUANTITY

ACCEPTED REJECTED

REMARKS

73154

QUANTITY

SHIP. TR #05907

3

RECEIVED
BYINSPECTED
BY

Dma

DATE

11/30/57

REJECTS RETURNED

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA, CALIF.

No. 11086

RECEIVED FROM

Lucas Aircraft Supply

DATE REC'D. 1-3-57

P.O. NO. 69209

VENDOR PACKING SLIP NO. 42045

CONTRACT
CODE NO.DRAWING
NUMBERDWG. DASH OR
STANDARD PART NO.DWG.
REV.LOT
NO.CLASS
NUMBEROPER
NUMBERBUY OUT
CODE NO.O ACCT. OR
W.O. NO.

R S.O. NO.

CHARGE TO
QUANTITY
RECEIVED

DRAWING NO. AND DESCRIPTION

QUANTITY

ACCEPTED REJECTED

REMARKS

25

730133-00

Bolt 1/4 X 28 X 2 12/32 UNF-30

25

RECEIVED
BYINSPECTED
BY

Dma

DATE

11/2/57

REJECTS RETURNED
ON SHIP. MEMO NO.